



Read this first

This kit may only be assembled by qualified personnel.
 Caution: When assembling be aware of the risk of injury from sharp edges on the rear of the FIEPOS unit. Assure that when the unit is finally installed any sharp edges on the back cannot be accessed and cannot cause injury. The power supply is mounted on a bracket with 4 screws of size M4 (UNC 8-32). For mounting the bracket use screws of equal or higher strength.

Product Description

The ZM.FPMBA-10 is a mechanical accessory to mount a device on a flat surface or panel. The ZM.FPMBA-11 is one package, including 50 mounting brackets.

Intended Use

This mechanical accessory is designed for FPT500, FPT300, FPH500 and FPS300 products.

Use the four screws (Pos 310 in drawing Screw positions) to mount the power supply to the mounting bracket. Use a torque of 1Nm/8.85 lbf inch to fasten the screws.

Technical Data	
Size (width x height x depth)	182x272x70mm
Weight	250g / 0.55lb

Assembly Instruction

